

Q10021408 - ARC-1883LP (newest FW) and 12x Samsung 843T 480GB foreground Init has been initialized instant in 0 seconds.

It is normal if this SSD support TRIM with return zero.

Unique solution ID: #1142

Author: Simone

Last update: 2015-08-24 09:34