

Q10031502 - After enabling ARC-1883 “SATA Power Up In Standby “ with WD HDD, a power down, and a new power up reports “failed disk”.

This is a bug of ARC-1883 PL firmware bug that can't response correctly the PM2 command to enable “SATA Power Up In Standby “. Areca has disabled this function from firmware version 1.52 date: 2014-12-25 or later.

Unique solution ID: #1021

Author: Simone

Last update: 2015-04-29 06:15