

Q10021401 - We have a problem with SuperMicro 24 Server with SAS Exp. Backplane, 2014-01-08 14:54:01 E2 Enclosure Temp Over Temp. The Logs said that the Enclosure is over temp.

It is a compatibility issue with SuperMicro backplane. Please disable the SES2 H/W monitor on the System Configurations from firmware version 1.52 to solve this kind of issue.

Unique solution ID: #1071

Author: Simone

Last update: 2015-08-24 09:15