

Q10031301 - Toshiba hard drives are not on your hardware compatibility list. Has there been any testing with Toshiba drives?

MKx001TRKB, Generic Firmware "1015" has the timeout issue without regular pooling the HDD.

Firmware „0106" has shortened the "write count processing time" compared to the Generic Firmware "1015".

Unique solution ID: #1241

Author: Simone

Last update: 2015-08-24 09:46