

Q10091304 - Using WD Red 2TB Raid drives, ARC-8050 has indicated Incomplete Raid on restart.

Adjust the "Stagger Power On Control" = 3s to provide more power up delay time for some WD Red 2TB Raid drives.

Unique solution ID: #1260

Author: Simone

Last update: 2015-08-24 10:00