

Q10041507 - Under CentOS 7.1, the "cli64" command throws an error claiming that the (arcmsr & sg) drivers are installed properly.

The Centos 7.x does not load sg module by default. Please modprobe sg and arcmr once to load it.

Unique solution ID: #1395

Author: Simone

Last update: 2015-08-24 08:41