

Q10031612 - DFI BT160 ATOM based MB with ARC-1200, system could not be boot up after install OS on it.

It is an issue on firmware version 1.51 BIOS code and had been fixed in the new BIOS code V1.24 2016-04-15 or later.

Unique solution ID: #1635

Author: Simone

Last update: 2022-01-06 08:13