

Q10011307 - Updating ARC1214BOOT.BIN via cli64 got "Firmware CRC Error". Updating f/w by web console via RJ45 and Archttp is working well.

This is F/W's bug. Update firmware to date:2013-06-11or later for this issue fixed.

Unique solution ID: #1263

Author: Simone

Last update: 2015-08-24 10:01