

Q10091307 - The HP Compaq Elite 8300 MBIOS=K01 v02.05 hangs when attempting to access ARC-1214-4I RAID controller BIOS configuration via TAB or F6.

Issue has been resolved by updating M/B BIOS.

Unique solution ID: #1271

Author: Simone

Last update: 2015-08-24 10:33