

Q10041204 - Installed an ARC-1882ix-12 with firmware version: V1.49 and created a 8 disk Raid 10, the controller card has stopped the foreground initialization at 99.6% and has been at that point.

It is a bug of time out issue on the "Write Same" command initialization. It has fixed on firmware version data:2012-04-20 or later. User can also disable the "Write Same For Initialization" on system configuration.

Unique solution ID: #1349

Author: Simone

Last update: 2022-01-06 08:29