

2018 to 2020

Q10151404 - OpenE (V7 UP12) got the kernelpanic/call trace errors during IO with ARC-1883.

This is an interrupt issue on linux kernel with ARC-1883. This has been fixed in linux source arcmsr-1.30.0X.18-20140417 driver version or later.

Unique solution ID: #1121

Author: Simone

Last update: 2015-08-24 09:28