

**2018 to 2020**

**Q10011305 - Do you know if the 1882 Windows  
2008 Server R2 driver ( arcm\_a64.sys v6.20.0.22)  
supports 64 bit addressing per this Microsoft  
Knowledge base article?**

**<http://support.microsoft.com/?id=2468345>**

The storport.sys is a Windows buildin driver and the article is used to explain how the hotfix solved the bug in storport.sys. It is independent of our driver. Our driver will call storport.sys, you may get problem on using our storport driver if the storport.sys issue has not been fixed. You should update Windows with latest service pack to make sure the storport.sys issue had been solved.

Unique solution ID: #1261

Author: Simone

Last update: 2015-08-24 10:00