

2018 to 2020

Q10091502 - Brand new Samsung 850 Pro 1TB SSD's are being detected as "FAILED" by the Areca Controller.

This is a firmware bug of Samsung 840 EVO and 850 Pro that can't response correctly the SSD cache control from the host. Areca has a workaround for this issue from firmware version 1.52 date: 2014-12-19 or later.

Unique solution ID: #1027

Author: Simone

Last update: 2015-08-24 08:47