

2018 to 2020

Q10071203 - Archttp 64 has a pretty bad memory leak using the latest firmware on an arc-1680-ix under a 3.2 linux kernel if I let the auto-refresh on the hardware information page stay open.

It has fixed by the Archttp version 2.1.2 or greater.

Unique solution ID: #1344

Author: Simone

Last update: 2022-01-06 08:29