

**2018 to 2020**

**Q10101601 - When I try to use the ARC-1882, the HP DL385 G5P computer shows an error: “Fatal PCI Express Error PCI Slot 1 B42/D00/F00 10 “.**

This issue can be fixed on ARC-1882 firmware version 1.52 date: 2016-1-28 or later.

Unique solution ID: #1554

Author: Simone

Last update: 2022-01-06 08:09