

2018 to 2020

**Q10031603 - The Innodisk 2.5" SATA SSD 3MG2-P
is not being detected or detected intermittently
while using our MB996SP-6SB with
ARC-1883IX-12 Controller.**

This compatible issue can be fixed on Innodisk 2.5" SATA SSD 3MG2-P new firmware.

Unique solution ID: #1591

Author: Simone

Last update: 2022-01-06 08:09