

2018 to 2020

Q10021612 - We have ARECA1883iX + 91-1883BA-T00B Bat, From CLI I see > Battery Status: 22% after 24hod.charging.

It is a known issue on firmware version 1.53 and had been fixed in the new firmware version. Please update your card with the latest firmware 1.54.

Unique solution ID: #1634

Author: Simone

Last update: 2022-01-06 08:13