

2018 to 2020

**Q10031612 - DFI BT160 ATOM based MB with
ARC-1200, system could not be boot up after
install OS on it.**

It is an issue on firmware version 1.51 BIOS code and had been fixed in the new BIOS code V1.24 2016-04-15 or later.

Unique solution ID: #1635

Author: Simone

Last update: 2022-01-06 08:13