

2018 to 2020

Q10041702 - Our customer is running Supermicro X9DRL-iF (BIOS 3.0a) und Areca-1883 (Firmware 1.54 - 2016-11-23), booting hangs at Supermicro BIOS Message B2.

This problem appears to be the 1.54 BIOS/firmware package. It only happens on special M/B. Reverting from 1.54 BIOS code to 1.53 BIOS code can resolve it.

Unique solution ID: #1648

Author: Simone

Last update: 2022-01-06 08:16