

2018 to 2020

Q10041704 - Supermicro X10SLQ-L will stuck at the BIOS Screen, won't continue to boot, if there are more than Areca volumes.

This problem appears to be the 1.54 BIOS/firmware package. It only happens on special M/B. Reverting from 1.54 BIOS code to 1.53 BIOS code can resolve it.

Unique solution ID: #1664

Author: Simone

Last update: 2022-01-06 08:17