

**2018 to 2020**

**Q10051808 - I have two WD4000FYYZ HDD, one Error Recovery Control seems disabled, other enabled.**

Controller will follow the setting the drive reported. The new drive could show disable if it is default disabled. You can modify the TLER setting in controller Advance Feature menu to 7 seconds for the WD4002FYYZ drive from disabled to 7 seconds (after restart).

Unique solution ID: #1763

Author: Simone

Last update: 2022-01-06 07:50