

**2018 to 2020**

**Q10031901 - If I try to create RAID volumes using  
Toshiba's HDD \* 6, MN05ACA800, it does not start  
the initialization.**

Setting the "Write Same for Initialization" to disabled rather than the default of SAS/SATA Write Same has resolved the initialization issue. You can find 'Write Same for Initialization' feature in web manager console, System Control > System Configuration menu.

Unique solution ID: #1773

Author: Simone

Last update: 2020-08-25 10:41