

2018 to 2020

Q10012003 - I have problem ARC-1882ix booting devices Firmware 1.56 on SuperMicro firmware 3.3, I'm searching for Firmware 1.52.

It is the bios compatible issue. The issue does not have to downgrade firmware back to 1.52, and only bios code needs to be downgraded. The old firmware packages can be found in our ftp site, and you just need to update the BIOS.BIN from older firmware package.

ftp://ftp.areca.com.tw/RaidCards/BIOS_Firmware/

Unique solution ID: #1894

Author: Simone

Last update: 2022-01-06 07:37