

2018 to 2020

Q10022003 - After ARC-1883 updates the FW from V1.55 to V1.56 on the HP Server DL 380 Gen9, the operating system from the HDD of the Server RAID can no longer be started. It remains only the option of a reboot with F10.

It is a compatible issue between the new bios code and this machine. We had ever modified the bios code for Mac boot issue. You can carry out the update to FW V1.56 without the * BIOS.BIN (only three files) to fix this compatible issue.

Unique solution ID: #1895

Author: Simone

Last update: 2022-01-06 07:37