

**2018 to 2020**

**Q10022012 - ARC-1203-2I firmware version  
1.56-2010-07-30 with SSDs under Win10 always  
appears SSD missed problem with cyclic restarts  
but without issue under 1.54.**

This is a bug of firmware version 1.56-2010-07-30. It can be fixed by firmware version 1.56 date: 2020-11-23 or later.

Unique solution ID: #1931

Author: Simone

Last update: 2022-01-06 07:39