

2015 to 2017

Q10021404 - When removing any of the Seagate ST2000NM0033, and re-inserting it on ARC-1214 is sometimes not detected. After rebooting, the HDD is detected OK.

This is a compatible issue with Marvell ROC and has been fixed in ARC-12x4 firmware version 1.52 date: 2014-3-31 or later. This HDD works fine using the ARC-1213/1680/1882 controllers.

Unique solution ID: #1108

Author: Simone

Last update: 2015-08-24 09:25