

2015 to 2017

Q10031506 - If 1883i and 1883LP enabled “SES2 support” on BPN-SAS2-826EL1 backplane, then, reboot will generate error message “E2 unknown power error”.

Please disable the SES2 H/W minitor on the System Configuration to ignore the compatibility.

Unique solution ID: #1235

Author: Simone

Last update: 2015-08-24 08:42