

**2015 to 2017**

**Q10051502 - Roaming 3Gb/s SATA HDD from  
ARC-1680 to ARC-1883ix-24 Raid Controller, the  
new ARC-1883 does not "see" any of this drives  
connected.**

It is a compatible issue between some 3Gb drives and 12Gb controllers. Using the link command to set the expander link speed from 12Gb to 6Gb.

Unique solution ID: #1023

Author: Simone

Last update: 2015-04-29 06:19