

2015 to 2017

Q10031202 - I have a supermicro database server with ARC-1680. It have lost connection to the sas expander backplane (in the same chassis):

Enclosure#3 : LSILOGICSASX28 A.0 7015(0:8).The log is full of errors like this:

2012-01-18 08:55:48 Enc#3 SES2Device Time Out Error

Please disable SES2 function to solve the issue from LSI expander firmware.

Unique solution ID: #1335

Author: Simone

Last update: 2022-01-06 08:27