

2015 to 2017

Q10061203 - Installing RHEL 6.2 doesn't work with the ARC-1882i controllers plugged in X8DTH-IF-B BIOS Version: 2.0c. It start to load of installer got stuck at "Waiting for hardware initialization".

BIOS update to R2.1a solved this issue.

Unique solution ID: #1343

Author: Simone

Last update: 2022-01-06 08:28