

2015 to 2017

**Q10011111- Is Seagate ST3500414SS SAS2 drives compatible with ARC-1880i controller? I got many time outs and the kernel tries to reset the bus.
“executing bus reset eh...”.**

It was caused by an extremely slow format speed on ST3500414SS with 0006 firmware. Sequential read/write is normal, but problem happens only while formatting. Problem can be reproduced with both Areca and LSI RAID cards.

Unique solution ID: #1427

Author: Simone

Last update: 2015-08-25 04:14