

2015 to 2017

Q10011112 - Under VMWare ESXi 5.0, Areca Intel IOP series RAID controllers work correct on SuperMicro X9SCA-F BIOS Version: 1.1a. But it can not work with LSI ROC controller.

It is a bug from X9SCA-F BIOS Version: 1.1a. We have a workaround firmware to bypass this bug. But we need to sacrifice one function.

Unique solution ID: #1434

Author: Simone

Last update: 2015-08-25 04:15