

**2015 to 2017**

**Q10011703 - Every time hot swap WD gold drive  
(WD4002FYYZ) drive on ARC-1203-8i, all other  
drives will be kicked out.**

This issue has fixed, and is included in the ARC-1203 firmware version  
1.54 data: 2017-02-14 or later.

Unique solution ID: #1653

Author: Simone

Last update: 2022-01-06 08:17