

2015 to 2017

Q10091704 - Customer has base supermicro system with 4 working 24bay jbods from AIC. If he connects a fifth chassis some drives get timeouts.

ARC-1680 can connect upto 7 expanders, but we suggest customers connect upto 4 expanders in our experience. The SAS bus may be occupied by too many SATA drives and result timeout errors.

Unique solution ID: #1669

Author: Simone

Last update: 2022-01-06 08:18