

**2015 to 2017**

**Q10041706 - ARC-1264iL have time-out and drop  
drive issue on FW:V1.54 2016-11-23 and  
WD6002FRYZ.**

This compatibility issue only happens on 1.54\_2016\_11\_23 firmware version. It has been fixed on 1.54\_2017\_03\_29 or later version.

Unique solution ID: #1693

Author: Simone

Last update: 2022-01-06 08:20