

2015 to 2017

Q10011401 - I'm trying to build a RAID 6 with a Mix of Samsung SSD 840 EVO and Pro. The initialization gets to 99.8% or 99.9% done and then stops and never completes. But there is no issue on SSD 840 Pro.

It is a TRIM support related issue. This problem happens only when you use different SSDs with different TRIM support ability. This behavior can be solved by firmware version 1.52, date 2014/1/20 or later.

Unique solution ID: #1070

Author: Simone

Last update: 2015-08-24 09:15