

**2018 to 2020**

**Q10011805 - When powering on and the  
ARC-1203-2I RAID-BIOS starts, the firmware  
accepts absolutely no input from keyboard using  
Asus Mainboard P10S-V/4L BIOS3103.**

You can make an USB-Boot stick with the good old MS-DOS, downloaded the latest BIOS from Asus and flashed the Mainboard to fix this issue.

Unique solution ID: #1744

Author: Simone

Last update: 2022-01-06 07:40