

2014

**Q10131404 - I am not able to upgrade the 1.51
firmware to the recent firmware 1.52 on
ARC1882.**

Update firmware from 1.51 to 1.52 firmware must update FIRM file first, and restart machine once to be able update the BIOS code. You can find the detail update sequence in the readme file included in the firmware package.

Unique solution ID: #1119

Author: Simone

Last update: 2015-04-30 08:49