

**2014**

**Q10101410 - Does ARC-1883LP controller support a drive connected on the expander out port from Supermicro CSE-826BE1C-R920LPB chassis?**

Areca's LED lighting function via SES2 protocol. In case hard disk didn't response RAID card a SES2 information on SES2 mode then hard disk will be failed. Firmware version 1.52 date: 2014-10-28 or later allows device directly connected expander out port recognized by RAID controller.

Unique solution ID: #1161

Author: Simone

Last update: 2015-08-24 09:37