

2014

Q10011111- Is Seagate ST3500414SS SAS2 drives compatible with ARC-1880i controller? I got many time outs and the kernel tries to reset the bus. "executing bus reset eh...".

It was caused by an extremely slow format speed on ST3500414SS with 0006 firmware. Sequential read/write is normal, but problem happens only while formatting. Problem can be reproduced with both Areca and LSI RAID cards.

Unique solution ID: #1427

Author: Simone

Last update: 2015-08-25 04:14