

2014

Q10091012 - When using various LSI 2108 controllers from LSI and Areca (ARC-1880 series) on the X7SBE motherboard, none of the LSI 2108-based controllers post. How can this be fixed?

Please contact SuperMicro technical support to request BIOS X7SB4_T2240 which fixes this issue. The Supermicro FAQ KB said that you can contact with them for a bios

X7SB4_T2240. <http://www.supermicro.com/support/faqs/results.cfm?id=48>

Unique solution ID: #1471

Author: Simone

Last update: 2022-01-06 08:03