

2014

**Q10121012 - I learned from the Web that the
ARC-1880 has issues with the Mac Pro, and that
Areca is already working to fix this issue.**

Please check the serial number on the controller which include or later than below serial number. It has fixed the MacPro hardware detective issue.

ARC-1880IXL-12: Y039CACUAR300013

ARC-1880IXL-8: Y039CACTAR200001

ARC-1880IX-12: Y039CACQAR300001

ARC-1880IX-16: Y039CARUAR600001

ARC-1880IX-24: Y039CAC SAR800001

ARC-1880X: Y038CACPAR200070

ARC-1880I: Y039CACOAR200001

Unique solution ID: #1474

Author: Simone

Last update: 2022-01-06 08:03