

**Q10041106 - Pull out a drive that was failing.  
Replace it with a better drive of the same  
capacity. Hot spare immediately became part of  
the raid set. New drive immediately became a hot  
spare. Volume State is listed as 'Need Rebuild',  
but nothing appears to be happening.**

To decrease the risk of data lost, firmware process background tasks is in two conditions only:

1. Stay in controller bios manager console

or

2. In the operating system and the controller driver is loaded.

The array status shows “need rebuild” mean the hot-spare had been successfully added into the array, but the current system status does not meet the requirement.

Unique solution ID: #1402

Author: Simone

Last update: 2015-08-25 04:07