

Q10021112- ARC-1882 as a bootable device will hang on the “Verifying DMI Pool” page of motherboard bios initialization. No-boot device is just fine.

It is a bug on the ARC-1882 ROC controller and update BIOS and firmware to workaround it.

Unique solution ID: #1435

Author: Simone

Last update: 2015-08-25 04:16