

2021 to 2022

**Q30011505 - ARC-8040 with ARC-1320-8X is poor
AJA performance can after HBA loads BIOS
default setting.**

ARC-1320 BIOS Load default will set the "Max. Command Xfer Length'=4M

"Max. Command Xfer Length'=4M will cause the AJA poor performance.

Please set it to 1M to get better performance.

Unique solution ID: #1155

Author: Simone

Last update: 2015-08-24 09:49