

Q80012002 - Customer has an issue reported about daisy chain 2x ARC-8050T3-8 units from one Thunderbolt 3 port on the new Mac Pro (2019).

Customer report after disconnecting the power cable from both units and then restarting fixed the issue.

Unique solution ID: #1907

Author: Simone

Last update: 2022-01-06 07:20