

**2021 to 2024**

**Q50012411 - Areca ARC-8028-24 the disk drive number/id's associated with each expander slot do not run in sequence. Why do the Drive Id's not match their physical connection order?**

Due to the limitation of circuit layout, it is normal that channel numbers are mismatch from phy numbers. These phy numbers are used for firmware troubleshooting.

Unique solution ID: #2051

Author: Simone

Last update: 2024-11-20 08:35