

Q50011605 - LSI MSM locate command doesn't work on 8028 expanders.

This issue has been fixed on LSI Phase 11 SAS3 Package Firmware.

Unique solution ID: #1612

Author: Simone

Last update: 2021-02-04 10:46