

Q80052208 - Hyper terminal connects to ARC-8050T3U, using port 992, get halted all the time, how to make connection?

The default telnet port is 993 for TLS connection. Since hyper terminal does not support TLS, please change the controller telnet port setting to 23 for hyper terminal management.

Unique solution ID: #1999

Author: Simone

Last update: 2022-08-11 05:28