

Q80032009 - Does ARC-8050T3-SAN RAID storage have any issue with Gigabyte Z390 Designare TRX40 M/B?

It is a motherboard BIOS issue. This motherboard bios has problem on supporting thunderbolt devices with two bridge layers. We had double checked with Gigabyte Z170X motherboard, no similar issue found. This Z170X motherboard can recognize 8050SAN without problem.

Unique solution ID: #1924

Author: Simone

Last update: 2022-01-06 07:21